COMPLETION REPORT

1. Name of Work : **UGD MAINTENANCE IN SIDEDAHALLI VILLAGE LIMIT IN BAGALAGUNTE IN WARD NO. 14 T.DASARAHALLI SUB DIVISION**

2. Sanctioned Estimate No. & Dt : EE/DD/TS/06/17-18, dt:-27-04-2017

3. Head of Account which is Chargeable : P-3158

4. Work Order No. & Dt : EE/DD/WO/129/2017-18 dt: 21-6-17

5. Name of Contractor : **THE TECHNICAL MANAGER (WEST), KRIDL**

6a. Time stipulated for completion of work : 90 days.

b. Delay in execution of work : -- Nil

7. Measurement recorded in : M.B. No. 582/17-18 Page No. 58111 to 58115

8. Check measurement of the Asst. : M.B. No. 582/17-18

Asst. Exe. Eng. / Exe. Eng : Page No. 58111 to 58115

9. Name of the Office / Official incharge of the work : AEE T.Dasarahalli Sub Division

10. a) Asst. Engineer : D.S.

b) Asst. Exe. Engineer : Shivkumar odegar

Sanctioned estimated amount	Amount claims as per actually vide as per bills	DIFFERENCE	
		Excess	Savings
20-00 Lakhs	19,96,632.00	—	3,368/—

1) Certified that the above work has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

ASST. ENGINEER

ASST. EXECUTIVE ENGINEER
Dasarahalli SUB DIVISION
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Division, Bangalore-57.

ACCOUNTS SUPTD. ( )